



VOLUNTEER MARINE RESCUE WHITSUNDA

Module : Head Injury
Type: SOP
Version: 1

STANDARD OPERATING PROCEDURES (SOP) HEAD INJURY

1. Introduction

This SOP describes the procedures to prevent head Injuries on VMR1.
It is the responsibility of every crew member to follow this procedure.

2. Reference

VMR Training – Risk Assessment 23 July, 2017.

3. Detailed Procedures

Be aware of low head room in forward cabin and Flybridge supports at aft end of main cabin.

Warnings signs to be installed.

Cushioning to be fitted to vulnerable points.

4. Summary

If we all follow these guidelines we will be less likely to have problems/injuries whilst accessing the foredeck.

AUTHORISED BY: Mal Priday _____ **President**

Geoff Fitzsimmons _____ **Senior Skipper**